

Contents

Editor's Preface XVII
List of Contributors XIX

1	Introduction	1
	<i>Andriy M. Gusak</i>	
2	Nonequilibrium Vacancies and Diffusion-Controlled Processes at Nanolevel	11
	<i>Andriy M. Gusak</i>	
2.1	Introduction	11
2.2	Beyond Darken's Approximation	12
2.3	The Model for Regular Chains of Ideal Vacancies Sinks/Sources	17
2.4	Description of Interdiffusion in Alloys at Random Power of Distributed Vacancy Sinks	20
2.5	Linear Phase Growth and Nonequilibrium Vacancies	22
2.6	Intermetallic Layer Growth at Imposed Current and Nonequilibrium Vacancies Damping Effect	25
2.7	Possible Role of Nonequilibrium Vacancies in Spinodal Decomposition	26
2.8	Nanoshell Collapse	29
2.9	The Role of Nonequilibrium Vacancies in Diffusion Coarsening	32
2.10	Conclusions	34
	References	34
3	Diffusive Phase Competition: Fundamentals	37
	<i>Andriy M. Gusak</i>	
3.1	Introduction	37
3.2	Standard Model and the Anomaly Problem	37
3.3	Criteria of Phase Growth and Suppression: Approximation of Unlimited Nucleation	45
3.4	Incubation Time	47
3.5	Should We Rely Upon the Ingenuity of Nature? Nucleation Problems and Meta-Quasi-Equilibrium Concept	49

3.6	Suppression of an Intermediate Phase by Solid Solutions	52
3.6.1	Unlimited Nucleation	53
3.6.2	Finite Rate of Nuclei Formation	54
3.7	Phase Competition in a Model of Divided Couple	55
	References	59
4	Nucleation in a Concentration Gradient	61
	<i>Andriy M. Gusak</i>	
4.1	Introduction	61
4.2	Nucleation in Nonhomogeneous Systems: General Approach	63
4.3	Thermodynamics of the Polymorphic Mode of Nucleation in a Concentration Gradient	65
4.3.1	Homogeneous Nucleation: General Relations	65
4.3.2	Spherical Nuclei	66
4.3.3	Ellipsoidal Nuclei	68
4.3.4	MC Simulations of the Shape of the Nucleus	70
4.3.5	Stress Effects	71
4.4	Thermodynamics of the Transversal Mode of Nucleation in a Concentration Gradient	74
4.4.1	Homogeneous Nucleation: General Relations	74
4.5	Thermodynamics of the Longitudinal Mode of Nucleation in a Concentration Gradient	79
4.6	Nucleation in Systems with Limited Metastable Solubility	81
4.6.1	Nucleation of a Line Compound at the Interface During Interdiffusion	82
4.6.2	Nucleation in between Dilute Solutions	86
4.6.3	Nucleation in between Two Growing Intermediate Phase Layers	86
4.6.4	Nucleation in between a Growing Intermediate Phase and a Dilute Solution	88
4.6.5	Application to Particular Systems	91
4.7	Conclusions	95
	References	97
5	Modeling of the Initial Stages of Reactive Diffusion	99
	<i>Mykola O. Pasichnyy and Andriy M. Gusak</i>	
5.1	Introduction	99
5.2	First Phase Nucleation Delay in Al–Co Thin Films	100
5.2.1	The Problem of Nucleation in a Concentration Gradient Field	101
5.2.2	Basic Model	102
5.2.3	Transversal Mode	105
5.2.4	Polymorphic Mode	107
5.2.4.1	Polymorphic Mode without Shape Optimization	108
5.2.4.2	Polymorphic Mode with Shape Optimization	109
5.2.5	Discussion and Conclusions	110

5.3	Kinetics of Lateral Growth of Intermediate Phase Islands at the Initial Stage of Reactive Diffusion	112
5.3.1	Problem Formulation	112
5.3.2	Physical Model	114
5.3.3	Numerical Results	116
5.3.4	Analytical Solution for the Steady State	117
5.3.5	Asymptotic Thickness of an Island	118
5.3.6	Estimates	119
5.3.7	Conclusions	121
5.4	MC-Scheme of Reactive Diffusion	121
5.4.1	Formulation of the Problem	121
5.4.2	The Model	122
5.4.3	Nucleation of Phase A_2B_1 at the Interface $A-A_1B_2$	124
5.4.4	Competitive Nucleation of Phases A_1B_2 and A_2B_1 at the Interface $A-B$	129
5.4.5	Lateral Competition	131
5.4.6	Conclusions	131
	References	132
	Further Reading	133
6	Flux-Driven Morphology Evolution	135
	<i>Andriy M. Gusak</i>	
6.1	Introduction	135
6.2	Grain Growth and Ripening: Fundamentals	136
6.2.1	Main Approximations of the LSW Approach	136
6.2.2	Traditional Approaches to the Description of Grain Growth	138
6.3	Alternative Derivation of the Asymptotic Solution of the LSW Theory	139
6.4	Flux-Driven Ripening at Reactive Diffusion	142
6.4.1	Experimental Results	143
6.4.2	Basic Approximations	144
6.4.3	Basic Equations	145
6.5	Flux-Driven Grain Growth in Thin Films during Deposition	148
6.5.1	“Mushroom Effect” on the Surface of a Pair of Grains: Deterministic Approach	150
6.5.2	Analysis of Flux-Driven Grain Growth	151
6.5.3	Stochastic Approach	154
6.5.4	Monte Carlo Simulation of Flux-Driven Grain Growth	155
6.5.5	Lateral Grain Growth in Aluminum Nanofilm during Deposition	156
6.5.5.1	Hillert’s Model	160
6.5.5.2	Models Leading to a Rayleigh Distribution	161
6.5.5.3	Pair Interaction Model (Di Nunzio)	161
6.6	Flux-Induced Instability and Bifurcations of Kirkendall Planes	163
6.6.1	Kirkendall Effect and Velocity Curve	164
6.6.2	Stable and Unstable K-Planes	165

6.6.3	Experimental Results	166
6.6.4	General Instability Criterion	168
6.6.5	Estimation of Markers' Distributions Near the Virtual K-Plane	169
6.6.6	Spatial Distribution of Markers	170
6.6.7	Possible Alternative to the Multilayer Method	171
6.7	Electromigration-Induced Grain Rotation in Anisotropic Conducting Beta Tin	173
6.8	Thermomigration in Eutectic Two-Phase Structures	178
6.8.1	Thermomigration Induced Back Stress in Two-Phase Mixtures	183
6.8.2	Thermomigration-Driven Kirkendall Effect in Binary Mixtures	184
6.8.3	Stochastic Tendencies in Thermomigration	185
	References	186
7	Nanovoid Evolution	189
	<i>Tatyana V. Zaporozhets and Andriy M. Gusak</i>	
7.1	Introduction	189
7.2	Kinetic Analysis of the Instability of Hollow Nanoparticles	191
7.2.1	Introduction	191
7.2.2	Mechanism of Nanoshell Shrinkage	192
7.2.3	Models of Nanovoid Shrinkage	194
7.2.3.1	Model 1: Shrinkage of Pure Element Nanoshells	195
7.2.3.2	Model 2: Shrinkage of a Binary Compound Nanoshell with Steady State Approximation for Both Vacancies and B Species	197
7.2.3.3	Model 3: Steady State and Non-Steady State Vacancies for Component B	200
7.2.3.4	Model 4: Non-Steady State Vacancies and Atoms	204
7.2.4	Segregation of Pure B at the Internal Surface	205
7.2.5	Kinetic Monte Carlo Simulation of Shrinkage of a Nanoshell	206
7.2.5.1	Model 1MC: Pure B-Shell in Vacuum	207
7.2.5.2	Model 2MC: Ordered IMC Nanoshell in Vacuum	208
7.2.6	Influence of Vacancy Segregation on Nanoshell Shrinkage	208
7.2.7	Summary	215
7.3	Formation of Compound Hollow Nanoshells	216
7.3.1	Introduction	216
7.3.2	Model of Nanoshell Formation	216
7.3.3	Simplified Analysis of the Competition Between "Kirkendall-Driven" and "Curvature-Driven" Effects	218
7.3.4	Rigorous Kinetic Analysis	220
7.3.5	Results and Discussion	225
7.3.6	Summary	228
7.4	Hollow Nanoshell Formation and Collapse in One Run: Model for a Solid Solution	229
7.4.1	Introduction	229
7.4.2	Shrinkage	229

7.4.3	Formation of a Hollow Nanoshell from Core–Shell Structure without the Influence of Ambient Atmosphere	233
7.4.4	Results of the Phenomenological Model	234
7.4.5	Monte Carlo Simulation of the Vacancy Subsystem Evolution in the Structure “Core–Shell”	238
7.4.5.1	Formation of a NanoShell in a MC simulation	239
7.4.5.2	Crossover from Formation to Collapse	239
7.4.5.3	Shrinkage and Segregation Kinetics in an MC Simulation	241
7.4.6	Summary	241
7.5	Void Migration in Metallic Interconnects	245
7.5.1	Hypotheses and Experiments	245
7.5.2	The Model	248
7.5.3	Results	249
7.5.3.1	Migration of Voids in Bulk Cu and Determination of the Calibration Factor between MCS and Real Time	249
7.5.3.2	Void Migration Along the Metal/Dielectric Interface	250
7.5.4	Simplified Analytical Models of Trapping at the GBs and at the GB Junctions	253
7.5.5	Summary	255
	References	256
8	Phase Formation via Electromigration	259
	<i>Semen V. Kornienko and Andriy M. Gusak</i>	
8.1	Introduction	259
8.2	Theory of Phase Formation and Growth in the Diffusion Zone at interdiffusion in an External Electric Field	260
8.2.1	External Field Effects on Intermetallic Compounds Growth at Interdiffusion	260
8.2.2	Criteria for Phase Suppression and Growth in an External Field	267
8.2.3	Effect of an External Field on the Incubation Time of a Suppressed Phase	270
8.2.4	Conclusions	271
8.3	Effects of Electromigration on Compound Growth at the Interfaces	272
8.4	Reactive Diffusion in a Binary System at an Imposed Electric Current at Nonequilibrium Vacancies	275
8.4.1	Equation for the Growth of an Intermediate Phase taking into Account Nonequilibrium Vacancies	275
8.4.2	Analysis of the Equation for the Rate of Intermediate Phase Growth in Limiting Cases	279
8.4.3	Numerical Solution of the Equation for the Intermediate Phase Rate of Growth	281
8.4.4	Conclusion	286
	References	286

9	Diffusion Phase Competition in Ternary Systems	289
	<i>Semen V. Kornienko, Yuriy A. Lyashenko, and Andriy M. Gusak</i>	
9.1	Introduction	289
9.2	Phase Competition in the Diffusion Zone of a Ternary System	289
9.2.1	Phase Competition in the Diffusion Zone of a Ternary System with Two Intermediate Phases	290
9.2.2	Influence of Pt on Phase Competition in the Diffusion Zone of the Ternary (NiPt)–Si System	295
9.2.2.1	Basic Considerations	295
9.2.2.2	Effect of Pt on Phase Competition in the Diffusion Zone of Ni–Si	297
9.2.2.3	Calculations and Discussion	300
9.3	Ambiguity and the Problem of Selection of the Diffusion Path	302
9.3.1	General Remarks	302
9.3.2	Analytical Solution of the Simplified Symmetric Model	304
9.3.3	Numerical Calculations for a Complex Model	309
9.3.4	Conclusions	320
9.4	Nucleation in the Diffusion Zone of a Ternary System	321
9.4.1	Model Description	321
9.4.2	Algorithm and Results for the Model System	325
9.4.3	Discussion	327
	References	329
	Further Reading	331
10	Interdiffusion with Formation and Growth of Two-Phase Zones	333
	<i>Yuriy A. Lyashenko and Andriy M. Gusak</i>	
10.1	Introduction	333
10.2	Peculiarities of the Diffusion Process in Ternary Systems	334
10.2.1	Notations	334
10.2.2	Thermodynamic Peculiarities	335
10.2.3	Diffusion Peculiarities	336
10.2.4	Types of Diffusion Zone Morphology in Three-Component Systems	337
10.3	Models of Diffusive Two-Phase Interaction	340
10.3.1	Model Systems	341
10.3.2	Phenomenological Approach to the Description of Interdiffusion in Two-Phase Zones	345
10.3.3	Choice of the Diffusion Interaction Mode	348
10.4	Results of Modeling and Discussion	350
10.4.1	One-Dimensional Model of Interdiffusion between Two-Phase Alloys	350
10.4.2	The Problem of Indefiniteness of the Final State	352
10.4.3	Diffusion Path Stochastization in the Two-Phase Region	353
10.4.4	Invariant Interdiffusion Coefficients in the Two-Phase Zone	354

10.4.5	Conclusions	356
	References	356
	Further Reading	358
11	The Problem of Choice of Reaction Path and Extremum Principles	359
	<i>Andriy M. Gusak and Yuriy A. Lyashenko</i>	
11.1	Introduction	359
11.2	Principle of Maximal Entropy Production at Choosing the Evolution Path of Diffusion-Interactive Systems	359
11.3	Nonequilibrium Thermodynamics: General Relations	361
11.3.1	Isolated Systems	361
11.3.2	System in a Thermostat	363
11.3.3	Inhomogeneous Systems: Postulate of Quasi-Equilibrium for Physically Small Volumes	364
11.3.4	Extremum Principles	366
11.4	Application of the Principles of Thermodynamics of Irreversible Processes: Examples	368
11.4.1	Criterion of First Phase Choice at Reaction–Diffusion Processes	368
11.5	Conclusions	378
	References	379
12	Choice of Optimal Regimes in Cellular Decomposition, Diffusion-Induced Grain Boundary Migration, and the Inverse Diffusion Problem	381
	<i>Yuriy A. Lyashenko</i>	
12.1	Introduction	381
12.2	Model of Self-Consistent Calculation of Discontinuous Precipitation Parameters in the Pb–Sn System	382
12.2.1	General Description of the Model Systems	384
12.2.2	Model Based on the Balance and Maximum Production of Entropy	387
12.2.2.1	Phase Transformations and Law of Conservation of Matter	388
12.2.2.2	Calculation of the Driving Force	389
12.2.2.3	Calculation of Energy Dissipation in the Transformation Front along the Precipitation Lamella	389
12.2.2.4	Calculation of Energy Dissipation Close to the Transformation Front	393
12.2.3	Calculation of Entropy Production Taking into Account Grain Boundary Diffusion and Atomic Jumps through the Grain Boundary	400
12.2.3.1	Optimization Procedure and Calculation Results	401
12.3	Model of Diffusion-Induced Grain Boundary Migration (DIGM) Based on the Extremal Principle of Entropy Production by the Example of Cu–Ni Thin Films	405
12.3.1	Model Description	406

12.3.1.1	Mass Conservation and Thermodynamic Description	408
12.3.1.2	Calculation of the Entropy Production Rate due to Grain Boundary Diffusion	409
12.3.1.3	Calculation of the Driving Force	410
12.3.2	Results of Model Calculations for the Cu–Ni System	411
12.3.2.1	Determination of the Curvature of the Gibbs Potential	411
12.3.2.2	Diffusion Parameters of the System	412
12.3.2.3	Grain Boundary Mobility	412
12.3.2.4	Results of the Model Calculation for the Cu/Ni/Cu-Like System	412
12.4	Entropy Production as a Regularization Factor in Solving the Inverse Diffusion Problem	416
12.4.1	Description of the Procedure of the Inverse Diffusion Problem Solution for a Binary System	416
12.4.2	Results of Model Calculations	418
12.5	Conclusions	421
	References	422
	Further Reading	424
13	Nucleation and Phase Separation in Nanovolumes	425
	<i>Aram S. Shirinyan and Andriy M. Gusak</i>	
13.1	Introduction	425
13.2	Physics of Small Particles and Dispersed Systems	427
13.2.1	Nano-Thermodynamics	427
13.2.2	Production of Dispersed Systems	428
13.2.3	Anomalous Structures and Phases in DSs and Thermodynamic Estimates	428
13.2.4	Influence of DSs on the Temperature of the Phase Transformation	430
13.2.5	State Diagrams of DSs	431
13.2.6	Shift of the Solubility Limits in DSs	431
13.2.6.1	Depletion	432
13.2.7	Concluding Remarks	432
13.3	Phase Transformations in Nanosystems	433
13.3.1	Solid–Solid First-Order Phase Transitions	433
13.3.1.1	Geometry of a Nanoparticle and Nucleation Modes	433
13.3.1.2	Depletion Effect	435
13.3.1.3	Regular Solution	435
13.3.1.4	Change of Gibbs Free Energy	436
13.3.1.5	Minimization Procedure	437
13.3.1.6	Probability Factor of the Phase Transformation	439
13.3.2	Phase Diagram Separation	439
13.3.2.1	Variation of Temperature T	439
13.3.2.2	Transition Criterion, Separation Criterion	440
13.3.2.3	Varying R	441

13.3.2.4	Varying C_0	441
13.3.2.5	Phase Diagram	441
13.3.2.6	Size-Dependent Diagram and Solubilities in Multicomponent Nanomaterials	442
13.3.2.7	Critical Supersaturation	443
13.3.2.8	Concluding Remarks	444
13.4	Diagram Method of Phase Transition Analysis in Nanosystems	444
13.4.1	Gibbs's Method of Geometrical Thermodynamics	445
13.4.2	Nucleation of an Intermediate Phase	446
13.4.2.1	Phase Transition Criterion	446
13.4.2.2	Model of Intermediate Phase	446
13.4.2.3	Separation in a Macroscopic Sample: Equilibrium State Diagram	447
13.4.2.4	Separation in DSs: Size-Dependent Phase Diagram	448
13.4.2.5	Influence of Size on Limiting Solubility	449
13.4.2.6	Influence of Size of an Isolated Particle on the Phase Transition Temperature	449
13.4.2.7	Concluding Remarks	450
13.5	Competitive Nucleation and Growth of Two Intermediate Phases: Binary Systems	451
	Case 1	454
	Case 2	454
	Case 3 or Crossover Regime	455
13.5.1	Application to the Aluminum–Lithium system	456
13.5.2	Concluding Remarks	458
13.6	Phase Diagram Versus Diagram of Solubility: What is the Difference for Nanosystems?	458
13.6.1	Some General Definitions	461
13.6.1.1	What are the “solidus” and “liquidus”?	461
13.6.1.2	What is the “Limit of Solubility”?	461
13.6.2	Nanosized Solubility Diagram	462
13.6.2.1	Solubility Limit	462
13.6.2.2	Liquidus	462
13.6.2.3	Solidus	462
13.6.2.4	Nanosized Solubility Diagram	462
13.6.3	Nanosized Phase Diagram	463
13.6.3.1	Three Types of Diagrams	463
13.6.3.2	T – C Diagram at Fixed R	464
13.6.3.3	Varying R	465
13.6.3.4	Concluding Remarks	465
13.7	Some Further Developments	465
13.7.1	Solubility Diagram of the Cu–Ni Nanosystem	465
13.7.2	Size-Induced Hysteresis in the Process of Temperature Cycling of a Nanopowder	466

XVI | *Contents*

13.7.2.1	Concluding Remarks	468
13.A	Appendix: The Rule of Parallel Tangent Construction for Optimal Points of Phase Transitions	469
13.A.1	Resume	470
	References	471
	Index	475